


T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MCH# 3 Corner common to sections 36 AND 31-140-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. Maple W. Birch  
Diameter 7" 7"  
Bearing S73W S73E  
Distance 22 lks 12 lks

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1911 By A. W. Moulster  
Location filed Microfilm - Roll 105 BK 49 P. 24-25  
Monument set lost

Evidence of Subsequent Corner Restoration

Year of search 6/2001 By CCSO  
Found 2" ODIP, up 0.8', 7 1/2 S. of Lake shore.

could not get courses on new BIT'S

Bearing Trees, Reference Objects

Species Pop. B.Y.  
Diameter 7" 5"  
Bearing S-E S-W  
Distance 8.88' 4.90'

Bearing Trees, Reference Objects

R. Oak N. Pine  
28" 16"  
S46°W S44°E  
44.72'\* 36.85'\*

\*distance to double head nail

V, W-25

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - GREEN GABLES (B-23)  
W. J. SPAIN 1948

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_