


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4



O = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument POST C.C.

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species TAM. BL. OAK
Diameter 9" 9"
Bearing S66E S30W
Distance 44 LKS 108 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1978 By Co Hwy Dept
Location filed Co Rd # 122
Monument 3/4" I.P. replace

Evidence of Subsequent Corner Restoration
Year of search ? By STEVENSON RECORDS
1" IRON PIPE

Bearing Trees, Reference Objects
Species oak oak Birch
Diameter 6" 6" 12"
Bearing NNW NW NW
Distance 93.1' 101.4 87.8'

Bearing Trees, Reference Objects
18" W. OAK 8" R. OAK TEL. POLE
S62°W N 12°W S 31°W
70.88 99.39 17.60

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument Corner GPS CCSO 7/24/02
CCSO sd. 1" OPIP, up 1.5'

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____