


T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 17 Corner common to sections 8, 17



EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1865</u>		Year of search _____	By _____
Original monument <u>POST</u>		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species <u>ASPEN</u>	<u>ASPEN</u>	Species _____	
Diameter <u>6"</u>	<u>4"</u>	Diameter _____	
Bearing <u>S 77 1/2 W</u>	<u>N 59 W</u>	Bearing _____	
Distance <u>30 LKS</u>	<u>35 LKS</u>	Distance _____	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration	
Year surveyed <u>1916</u>	By <u>E.B. HORST</u>	Year of search _____	By _____
Location filed <u>COUNTY BOOK B' P 557-560</u>		<u>also on microfilm - roll 105 BK 61 P. 158</u>	
Monument <u>SET 2 X 4 B" BOILER FLUE</u>		<u>also on microfilm - roll 105 BK 59 P. 52-53</u>	
<u>1921 - E.B. HORST - COUNTY RESURVEY "E-36" I.M.</u>			
<u>1921, E.B. HORST, BOOK "X" P 441 SET HUB FROM BITS, IRON WAS PULLED BY SOMEONE SET I.M.</u>			
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>N. PINE</u>	<u>POPULAR</u>	_____	_____
Diameter <u>4"</u>	<u>6"</u>	_____	_____
Bearing <u>N 20 W</u>	<u>S 35-25 W</u>	_____	_____
Distance <u>28.2'</u>	<u>21.4'</u>	_____	_____
<u>1916 ties</u>			

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument June 2004 J. Leas # 42619
(left of Sur. Shows mon. found)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
