


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE R1 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	W. PINE	W. PINE	Trees	W. PINE	W. PINE
Diameter		10"	20"	15"		20"
Bearing		N75E	S70E	S75W		N45W
Distance		20 LKS	17 LKS	32 LKS		46 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By E. B. HORST  
Location filed COUNTY BOOK C P. 207

Monument Find Iron In Place  
1939 JOHN CURO - FND 2x48" IRON IN PLACE

1907- JOHN CURO BOOK B P. 433-411 FND OLD GOVT BT

STUMPS: 10" W. PINE N75E 20 LKS, 20" W. PINE S70E 17 LKS, 15" W. PINE S75W 32 LKS, 20" W. PINE N45W 46 LKS. SET 4x4x24" PINE POST

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search 1942 By JOHN CURO  
COUNTY BOOK D P. 293 FND 2x48" (APPROX. 1919)

1939 - JOHN CURO - COUNTY BOOK D P. 176 FND 2x48" I.P. W/CAP. AT P.L. ROS. E-W-N.

Bearing Trees, Reference Objects

W. OAK	W. PINE	W. OAK	POPULAR
9"	12"	10"	8"
N82-45E	S73-43E	S46-50W	N70-35W
154.28'	238.6'	59.75'	187.03'

1942 TIES

N-13

Subsequent Corner Restoration

Year surveyed 1978 By Co Hwy Dept  
Location filed Co Rd #122  
Monument 3/4" I.P. Inplace

Evidence of Subsequent Corner Restoration Found

Year of search NOV. 2000 By CCSO  
Fnd. in place; P.K. nail re-set post construction from Hwy ties. Located 1'S of E CSAH 5 and E C.R. 122

REF. TIES:

P. Pole	N 22° W	75.44' (exist. Hwy tie)
7" Spruce	N 28° E	123.27'
8" Ash	S 22° E	81.90' (exist. Hwy tie)
Guy Pole	S 35° W	61.82' (exist. Hwy tie)

Mar 2003 T. Freeman # 21367  
Cert. of Surv. shows Mon. Found

Corner GPS CCSO 7/18/02  
CCSO Fd. PK

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_