Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____

N¼ 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees

Species	W. Pine	W. Pine
Diameter	6"	6"
Bearing	S36E	N69W
Distance	4 LKS	5 LKS.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1939 By Jetta Cubo.

Location filed County Book "D" P. 196

Monument Fnd 2x48" IRON PIPE w/ CAP. ~~set~~ P.I.

Rds E-W - S

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Evidence of Subsequent Corner Restoration

Year of search 1972 By Co Hwy Dept.

Co Rd #45

1" I.P. in place

1960 - Co Hwy Dept - Co Rd #5

Found 2½" I.P. w/cap

Bearing Trees, Reference Objects

P.P.	Birch		
NE	10" SE		
72.0'	88.6'		
1960 TIES			

N-15

Subsequent Corner Restoration

Year surveyed 1998 By CCSO

Location filed

Monument set P.K. in place of Capped I.P.

It was removed prior to overlay.

11" W. Pine	N 70° E	217.01'
15" Basswood	S 30° E	107.88'
½" Rod	S 33° W	84.76'
8" Ash	S 65° W	139.95'
¾" Rod	N 54° W	90.73'
P. Pole	N 20° E	71.97'

* distances pulled to dbl. hd. nail

Mar 2003 T. Freeman #21367

Cert. of Surv. shows Mon. Found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____