


T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 31 Corner common to sections 29, 30, 31, 32

SMC #41



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>15"</u>	<u>18"</u>	_____
Bearing	<u>N 68 1/2 E</u>	<u>S 77 E</u>	_____
Distance	<u>346 LKS</u>	<u>294 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO, M.A. KEMP
Location filed COUNTY BOOK B" P 399-401
Monument FIND OLD GRANT BIT. STUMPS: 15" N. PINE N 68-30 E 346 LKS, 18" N. PINE S 77 E 294 LKS AND OLD STAKE SET 2x4@ 1. P. W/CAP.

Evidence of Subsequent Corner Restoration

Year of search 1965 By R.F. SCHNEIDER
COUNTY BOOK "D" P. 452 FIND CAPPED I.M.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

V-5

Subsequent Corner Restoration

Year surveyed 1924 By Miss Hux Dept.
Location filed R/W map in Recorder's Office
Monument Lothrop to Pine River. 1. P. w/cap 1001.3' W. of Q

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Jim Nielsen - Minn DOT 1903
Doc. # 267934
Found 2" capped pipe down 0.3'. Ties:
5" Tamarack S 56 E 53.83'; 8" Jack Pine
N 78 E 259.85'; Post 0.7' East; Ham
Lake 25' West.

May 2005 T. Freeman #21367
Cert. of Survey shows monument found