


Index No. J 19

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 14 Corner common to sections 11, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>N. PINE</u>	<u>W. PINE</u>	_____	_____
Diameter	<u>14"</u>	<u>12"</u>	_____	_____
Bearing	<u>S 66 E</u>	<u>N 80 E</u>	_____	_____
Distance	<u>50 LKS</u>	<u>47 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By N. D. GORMAN  
Location filed COUNTY BOOK 'B' P 469-471  
Monument END 2 1/4 X 4 1/8" GALV. I.P. SET BY CURO.  
IT IS W.C. 60' N OF TRUE 1/4 CORNER.

Evidence of Subsequent Corner Restoration

Year of search 1914 By John Curo  
microfilm - roll 115 BK 93 1, 28  
Set I.P. 60' N. of true corner for W.C.  
June 1909 Twp rd order shows no survey

also on microfilm - roll 115 BK 88 P 27-28,

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>Birch</u>	_____	_____
<u>12"</u>	<u>6"</u>	_____	_____
<u>N 87-30 E</u>	<u>S 55-30 W</u>	_____	_____
<u>44.38'</u>	<u>19.70'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_