


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 21 Corner common to sections 15, 16, 21, 22 N.C. 4.50 CH. SOUTH



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument Post w.c. 4.50 CH. SOUTH  
✓ ✓ 8.91 CH. WEST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Rearing Trees

Species	B. Pine	Aspen	Aspen
Diameter	<u>12"</u>	<u>2"</u>	<u>8"</u>
Bearing	<u>S82E</u>	<u>WEST</u>	<u>N 67 W</u>
Distance	<u>214 LKS.</u>	<u>20 LKS.</u>	<u>50 LKS.</u>
	<u>4.5 SOUTH</u>	<u>8.91 WEST</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1969 By DNR  
Location filed Map & notes in file  
Monument End 1 1/2" I.P. with stamped cap  
1 1/2" above ground in 16w area ± 150' E of Lake

Evidence of Subsequent Corner Restoration

Year of search 1927 By Bartlett, Green  
Microf. film - roll 115 BK 72 P. 42  
End I.M. in bag

Bearing Trees, Reference Objects

Species	w. pine	w. pine	J. Pine
Diameter	<u>3"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>South</u>	<u>NNE</u>	<u>ENE</u>
Distance	<u>5.70'</u>	<u>33.22'</u>	<u>16.14'</u>
	<u>Nail &amp; B.C.</u>	<u>N. B.C.</u>	<u>N. B.C.</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument May 2003 J. Freeman # 21367  
Cert. of Surv. shows more found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_