


Index No. V1

CASS COUNTY LAND CORNER RECORD



T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 31 Corner common to sections 30, 31

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1860
 Original monument POST

Bearing Trees			
Species	Bearing	Tree	Distance
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
<u>6"</u>	<u>6"</u>	<u>10"</u>	<u>8"</u>
<u>558W</u>	<u>N45W</u>	<u>S65E</u>	<u>N60E</u>
<u>53 LKS.</u>	<u>29 LKS.</u>	<u>56 LKS.</u>	<u>32 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1921 By E.B. Herbst
 Location filed micro film - roll 115 BK 85 P. 316
 Monument at 7950.2' from S. set 2848' I.M.

Evidence of Subsequent Corner Restoration
 Year of search July 1905 By _____
Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>J. Pine</u>	<u>J. Pine</u>	<u>Post</u>	
<u>12"</u>	<u>5"</u>		
<u>515W</u>	<u>545E</u>	<u>North</u>	
<u>126.4'</u>	<u>157.8'</u>	<u>21.8'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____