


Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Bearing Trees

Species	<u>B. GILEAD</u>	<u>B. GILEAD</u>	<u>B. GILEAD</u>	<u>B. GILEAD</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>10"</u>
Bearing	<u>S 37° E</u>	<u>N 35 1/2° W</u>	<u>N 52 1/2° E</u>	<u>S 57° W</u>
Distance	<u>10 LKS.</u>	<u>9 LKS</u>	<u>12 LKS</u>	<u>15 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1975 By Co. Hwy Dept

Location filed Co. Rd #40

Monument Found Corner

July 1905, Tax rd order shows no survey

Evidence of Subsequent Corner Restoration

Year of search Dec 2002 By CCSO

Found NE COR 33/140/31 2 1/4" ODIP
on end of fence line, up 0.6, 75 ±
E of E variety Lake Drive

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

W. Oak	W. Oak	W. Oak
8"	8"	6"
S 85° E	N 10° E	S 30° E
16.87° *	11.65° *	17.95° *

* Dist. to dbl head nail

V-13

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

May 2004 T. Freeman # 21367
cert. of Sur. Shows mon. Found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - JACK PINE SHORES
G. H. STEVENSON 1981

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____