Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 4 Corner common to sections 3, 4 AND 33, 34 - 142 - 25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	CEDAR	BIRCH	BIRCH	FIR
Diameter	6"	10"	12"	8"
Bearing	S3E	N45E	N32½W	S77W
Distance	8 LKS	30 LKS	12 LKS	28 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By J.H. FLYNN

Location filed COUNTY BOOK "D" P72

Monument FND CEDAR B.T. (DOWN) SET WOOD POST

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____