Index No. R23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____

N1/4 25 Corner common to sections 24, 25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Bearing Trees

Species	CEDAR	CEDAR
Diameter	8"	6"
Bearing	S50E	N80E
Distance	11 LKS	6 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____