


Index No. J 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 16 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Bearing Trees

Species	<u>FIR</u>	<u>ELM</u>	
Diameter	<u>8"</u>	<u>10"</u>	
Bearing	<u>N59E</u>	<u>S20W</u>	
Distance	<u>28 LKS</u>	<u>17 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1913 By J. H. FLYNN
Location filed COUNTY BOOK "C" P. 37
Monument TWO OLD GOVT BITS: STUB OF ELM & PART OF (DOWN) FIR

Evidence of Subsequent Corner Restoration

Year of search 1985 By USFS
Corner Certificate - Doc # 285566

Find stump of 1913 Bit, badly decayed - from this corner position fits well w/ rd; distance West - set 24x24" lip w/ stamped brass cap

Bearing Trees, Reference Objects

Species	<u>W. PINE STUMP</u>		
Diameter	<u>24"</u>		
Bearing	<u>S22-30W</u>		
Distance	<u>35'</u>		

Bearing Trees, Reference Objects

<u>Aspen</u>	<u>w. oak</u>	<u>Red line</u>
<u>12.5"</u>	<u>12.4"</u>	<u>11.0"</u>
<u>N16E</u>	<u>S22E</u>	<u>N16W</u>
<u>69.80'</u>	<u>33.95'</u>	<u>56.83'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Ken Whitehorn - USFS - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____