


Index No. L5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
E114 18 Corner common to sections 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species FIR SPRUCE
Diameter 10" 15"
Bearing N30E WEST
Distance 15 LKS. 25 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By J.H. FLYNN
Location filed COUNTY BOOK "K" P. 41
Monument FRD. CO. B. TS ?
1920, BEN CLARK, BOOK "C" P. 543 FRD. POST
SET 3x30" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1985 By Ken Whitehorn
Set 2 1/2" x 24" galvanized iron pipe with
3" brass tablet 12" below road surface.

Bearing Trees, Reference Objects

Species W. PINE
Diameter 16"
Bearing N42E
Distance 38'

Bearing Trees, Reference Objects

White Spruce Aspen
10" 5"
N 76 E S 65 E
62.62' 48.21'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1985 Cert. Filed by Ken Whitehorn
Doc # 286021

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____