Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 19 Corner common to sections 17, 18, 19, 20



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	SPRUCE	TAM.	CEDAR	TAM.
Diameter	8"	10"	10"	6"
Bearing	N24E	S30E	S25W	N18W
Distance	5 LKS	27 LKS	43 LKS	14 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY BOOK "C" P.543

Monument FND OLD TAM. S. B.T. AND 6" CEDAR S61-13W 26.8' SET HUB IN SIDE OF FIELD ON W. SIDE OF DITCH. 12' FROM BRIDGE. SET 3x30" I.M. P.544

Evidence of Subsequent Corner Restoration

Year of search 1993 10-22 By Lowell Schellack

Placed 2'6" x 24" galvanized iron pipe w/3" brass cap, top of monument 14" below road surface. 2-2-94 Doc. Filed by Lowell Schellack, RLS 15572, Doc #355094

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Balsam Poplar	Balsam Poplar	Power Pole	CMP Culvert
6"	7"		48"
N38E	N76W	S30W	S40E
99.67	110.80	135.28	17.28

Subsequent Corner Restoration

Year surveyed NOV 2000 By J. TORNES MN DNR/DR

Location filed DEER RIVER DNR

Monument FD MON 10" DOWN - RESOURCE GRADE GPS POSITION IS

LAT 47° 01' 12.706" N

LONG 93° 52' 50.563" W

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____