


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
E114 R1 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species SPRUCE CEDAR
Diameter 10" 10"
Bearing N35W N78E
Distance 11 LKS 19 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By J. H. FLYNN
Location filed COUNTY BOOK "C" P. 39
Monument FIND GOVT BITS: 10" SPRUCE STUMP N35W
10 LKS, 10" CEDAR N78E 19 LKS

Evidence of Subsequent Corner Restoration

Year of search 1985 By USFS
Corner Certificate - Doc # 285574
Find stump of 1913 Cedar - corner position
Fits well with 1913 distances - Set 2 1/2 x 2 1/2"
1 1/2" w/ brass cap

Bearing Trees, Reference Objects

Species CEDAR CEDAR
Diameter 11" 12"
Bearing S86E S89W
Distance 25' 25'

Bearing Trees, Reference Objects

Power Pole Tamarack Ash
9.4" 6.8" 4.0"
N68E S50E N76W
40.67' 97.13' 50.52'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Ken Whitehorn - USFS - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____