


Index No. P5

CASS COUNTY LAND CORNER RECORD

T. 14 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 19 Corner common to sections 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species SPRUCE FIR  
Diameter 10" 10"  
Bearing S37W N36E  
Distance 23 LKS 25 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1962 By DNR-Engineering  
Location filed map in file  
Monument set Railroad Spike

Evidence of Subsequent Corner Restoration

Year of search 6/2002 By CCSO  
Found 60 d spike down 0.3,  
2 1/2 E of E CR #133, on E 58th st.

Nov. 2000 J. TORRES, MN/DNR DEER RIVER,  
NOTHING FOUND - GPS (RESOURCE) POSITION

Bearing Trees, Reference Objects

Species? LAT 47° 00' 46.433 N.  
Diameter LONG 93° 52' 51.506 W  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

P. Pole N58°W 31.79' to dbl hd nail  
1 1/2" Balsam S60°E 33.54' to dbl hd nail  
6" Ash S84°W 70.73' to dbl hd nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_