141 R. 25 M. STH Coordinates: X  NE 39 Corner common to sections 20,71,78	29
	NG SURVEYS Original Evidence Found
Original Government Survey	
ear surveyed 1871	Year of search By
iginal monument fost	Monument found
Bearing Trees   TAM.   TAM.	Original Bearing Trees Found Species Diameter Bearing
Distance 22 LKS. 12 LKS 10 LKS 33 LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
ear surveyed By	Year of searchBy
ocation filed	
Monument	
Bearing Trees, Reference Objects pecies	Bearing Trees, Reference Objects
liameter	
• ••	
Regring	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Distance	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  fear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Gear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Gear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Gear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  ear surveyed By	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Tear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Tear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Tear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Tear surveyed By  Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Tear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  fear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Gear surveyed By Location filed	Evidence of Subsequent Corner Restoration Found