


T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
M.C.# 11 Corner common to sections 3,4



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____
Diameter	<u>10"</u>	<u>10"</u>	_____
Bearing	<u>N 60°W</u>	<u>S 47°E</u>	_____
Distance	<u>13 LKS.</u>	<u>7 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986 By Roger Mustonen
Location filed Corner Certificate - Doc # 295215
Monument End 1 1/2" l.p. - replaced w/ 2" VSPS monument w/ stamped brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Balsam</u>	<u>Ash</u>
Diameter	<u>18"</u>	<u>4"</u>	<u>11"</u>
Bearing	<u>S 76 1/2° E</u>	<u>S 13 1/2° W</u>	<u>S 89 1/2° W</u>
Distance	<u>30.91'</u>	<u>7.36'</u>	<u>12.08'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Roger Mustonen - 1987

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____