


Index No. D-24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5<sup>th</sup> Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 1/4 1 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1998 By CCSO  
Location filed CCSO  
Monument Fd. 1.5" ODIP down 0.4' North side of old driveway

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>Spruce</u>	<u>P. Pole</u>
Diameter	<u>26"</u>	<u>30"</u>	_____
Bearing	<u>S 39° E</u>	<u>N 68° E</u>	<u>N 11° E</u>
Distance	<u>24.32'</u>	<u>105.50'</u>	<u>14.02'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_