Index No. E R5

CASS COUNTY LAND CORNER RECORD

T. 141 R. R6 M. 5TH Coordinates: X _____ Y _____

NE 12 Corner common to sections 1, 12 AND 6, 7-141-R5



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Bearing Trees

Species	TAM.	TAM.	TAM.	
Diameter	10"	12"	14"	
Bearing	S5RE	S38W	N3W	
Distance	18 LKS	48 LKS	46 LKS	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO

Fd. USFS Gal. Pipe w/ brass cap, up 2.5'. Is Adjacent to corner fence post. 8' Steel sign post west, 2.0'.

Bearing Trees, Reference Objects

W. Oak	Black Ash	Elm Stump	W. Oak
13"	12"	6"	8"
N 48° W	N 51° E	S 16° E	S 79° W
145.30'	32.58'	77.60'	122.14'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____