


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	BIRCH	ASPEN	MAPLE
Diameter	10"	11"	7"
Bearing	N2E	N54W	S26E
Distance	39LKS	36LKS	76LKS

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986 By Roger Mustonen
Location filed Corner Certificate - Doc # 295218
Monument find 1 x 42" l.p. by old fence corner
replaced w/ 2" USFS monument

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Poplar	Ironwood	Maple	Maple
Diameter	6"	5"	7"	6"
Bearing	N58 1/2° W	N71 1/2° E	S38 1/2° E	S54 1/2° W
Distance	6.93'	16.74'	11.86'	25.06'

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Roger Mustonen - 1987

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____