Index No. 617 CASS COUNTY LAND CORNER RECORD	
T. 14/ R. 26 M. 574 Coordinates: X	
	SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1871 Original monument 1057	Year of search By
Original monument 1037	Monument found
Species SPRUCE CEDAR	Original Bearing Trees Found O = Corner
Diameter 6" 9"	Species
Bearing NBBW EAST	Bearing
Distance 8 CKS 6 CKS	Distance
Subsequent Corner Restoration	Fuidance of Calaman Co.
Year surveyed By	Evidence of Subsequent Corner Restoration Year of search By
Location filed	Tear or search
Monument	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	
DiameterBearing	
Distance	
Subsequent Corner Restoration Year surveyed By	Evidence of Subsequent Corner Restoration Found Year of searchBy
Location filed	
Monument	
-	
Remonumentation certificate prepared	By