Index No. J 23

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

N1/4 13 Corner common to sections 12, 13




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1871

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | FIR | SPRUCE PINE | | |
| Diameter | 16" | 8" | | |
| Bearing | S24E | N56W | | |
| Distance | 26 LKS | 34 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____