


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13 AND 7, 18-14-25



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument POST

Species	Bearing	Trees	
<u>CEDAR</u>	<u>T.M.</u>	<u>CEDAR</u>	<u>T.M.</u>
<u>6"</u>	<u>10"</u>	<u>8"</u>	<u>5"</u>
<u>N47 1/2 E</u>	<u>S77 3/4 W</u>	<u>N56 E</u>	<u>N66 W</u>
<u>18 LKS</u>	<u>25 LKS</u>	<u>18 LKS</u>	<u>17 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1919 By J.H. FLYNN
 Location filed COUNTY BOOK D P. 63
 Monument FOR ALL 4 GOVT BIT. STUMPS

Evidence of Subsequent Corner Restoration
 Year of search 1/2/1940 By Defant
USFS 874-9 on file in Cass Lake Office. Found 2" pipe 2' above ground, in ditch on E. side of road.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>BL. ASH</u>	<u>N37W</u>	<u>34.2'</u>
<u>BL. ASH</u>	<u>S42W</u>	<u>49'</u>
<u>BL. ASH (DEAD)</u>	<u>S66E</u>	<u>40.3'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Ash</u>	<u>N50°W</u>	<u>1.15 ch.</u>
<u>12"</u>	_____	_____
_____	_____	_____

J-25

Subsequent Corner Restoration
 Year surveyed 5/2002 By R. Main USFS
 Location filed Cass Lake Office
 Monument Found 2" x 48" iron pipe, in East ditch of old road. No evidence of original or subsequent BT's. Witness as follows:

Ash 7" N86°W, 34.00' to spk
Ash 7" N41°E, 14.40' to spk

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____