Index No. N11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

N1/4 21 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	MAPLE	BIRCH
Diameter	8"	8"
Bearing	N44W	S80W
Distance	45 LKS.	52 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1917 By ELYNN

Location filed COUNTY Book "D" P.55

Monument SET POST

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	LINDEN	LINDEN
Diameter	10"	12"
Bearing	S41E	N48W
Distance	30.2	44.6'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____