


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5th Coordinates: X _____ Y _____
N 1/4 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>TAM.</u>	<u>FIR</u>
Diameter <u>10"</u>	<u>6"</u>
Bearing <u>N36E</u>	<u>SSE</u>
Distance <u>22 LKS.</u>	<u>30 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1920 By JAMES FLYNN
Location filed COUNTY SURVEY E-1
Monument IRON MONUMENT
1920, J. FLYNN, COUNTY BOOK "C" P383 FND Govt B.T.
12" TAM. STUMP N36E 22 LKS Sct 1 1/2 x 48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 10/2002 By R. Main USFS
Fd 1 1/2" x 3' pipe laying down, found rust core and reset in old hole.

Bearing Trees, Reference Objects

Species <u>W. PINE STUMP</u>	_____
Diameter _____	_____
Bearing <u>N7W</u>	_____
Distance <u>16'</u>	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Ash</u>
<u>5"</u>	<u>7"</u>
<u>S 45° E</u>	<u>N 60° E</u>
<u>14.10'</u>	<u>15.07'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____