Index No. 0-P 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

MCH 5 Corner common to sections 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	TAM.		
Diameter	4"	4"		
Bearing	N 9W	N 17E		
Distance	930 LKS	925 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1919 By GLO (HARRINGTON)

Location filed SECRETARY OF STATE

Monument FND OLD GOVT B.T DEAD: TAM 6" N9W 930 LKS. M.C. FALLS IN LAKE SET 1"x36" IRON POST WITH BRASS CAP 139 LKS NORTH (91.74')

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	NO TREES SUITABLE	PITS IMPRACTICLE		
Diameter	SET 4"x6' CEDAR POST BY IRON			
Bearing	T141N	R26W		
Distance	S23	S24		

WC. M.C
1919

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____