


Index No. R 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	CEDAR	ASH	ASH	ASH
Diameter	6"	7"	6"	6"
Bearing	N W	N 7E	S 75E	S 3W
Distance	14 LKS	16 LKS	16 LKS	43 LKS

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By J.H. FLYNN  
Location filed COUNTY BOOK 'B' P. 510-511  
Monument FIND OLD GOVT BITS: CEDAR N 7E 16 LKS, ASPEN S 75E 16 LKS, ASH S 3W 43 LKS SET POST 1912 - FLYNN - BOOK 'D' P 59 - SAME INFO.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>W. BIRCH</u>	<u>BL. ASH</u>	_____
Diameter	<u>10"</u>	<u>7"</u>	_____
Bearing	<u>N 25 W</u>	<u>S 8 E</u>	_____
Distance	<u>61 LKS.</u>	<u>44 LKS.</u>	_____
	<u>40.26'</u>	<u>29.04'</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_