


Index No. T 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 R.5 Corner common to sections 25 and 30-141-2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>LINDEN</u>	<u>LINDEN</u>
Diameter <u>9"</u>	<u>4"</u>
Bearing <u>S80W</u>	<u>S40E</u>
Distance <u>18 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST  
Location filed COUNTY BOOK "C" P. 419  
Monument FIND GOVT B.T. 16" LINDEN S40E 12 LKS

Evidence of Subsequent Corner Restoration

Year of search Jul 2002 By R. Main MSFS  
Found so Iron wd 1.3 FT in young aspen stand  
Pipe is 2 1/2" in dia

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>W. Oak</u>
<u>6"</u>	<u>10"</u>
<u>N 38° E</u>	<u>S 80° W</u>
<u>14.85'</u>	<u>27.50'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_