


Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31 - 141-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN
Diameter 10"
Bearing N 1/2 E
Distance 1450 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY SURVEY E-1
Monument IRON MONUMENT
1921, COUNTY BOOK "C" P. 419, J. FLYNN SET 2 1/2 X 30" I.M. RECONSTRUCTION
IN ABOUT CENTER OF DITCH BANK.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____