


Index No. X-Y R1

CASS COUNTY LAND CORNER RECORD

T. 141 R. R6 M. 5TH Coordinates: X _____ Y _____
MC # 2 Corner common to sections 35,36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Bearing Trees	
Species <u>ELM</u>	<u>W. PINE</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>S40W</u>	<u>N53E</u>
Distance <u>65 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY SURVEY E-1"
Monument IRON MONUMENT
1921, J. FLYNN, COUNTY BOOK "C" P. 420 FWD 6x1 BT!
12" ELM (DOWN) S40W 43' SET 1 1/2 X 40" I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species <u>W. BIRCH</u>	<u>W. BIRCH</u>
Diameter <u>5"</u>	<u>6"</u>
Bearing <u>S57E</u>	<u>S13W</u>
Distance <u>4'</u>	<u>5.5'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1978
Doc. # 245625
Set 2" x 60" galvanized steel pipe with
brass cap. Ties: 11" Red Oak S86E 102.70';
6" White Oak S68W 22.30'; 6" Elm S17E
59.55'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____