


Index No. Y 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
5 1/16 Corner common to sections 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1978
Doc. # 245626
Set 2" x 60" galvanized steel pipe with
brass cap. Ties: 8" Ash S 66 E 44.80';
9" Ash S 27 E 67.80'; 5" White Oak
N 13 W 153.40'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____