Index No. Z 2-3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

MC # 24 Corner common to sections 31 AND 6-140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam.	Tam.		
Diameter	5"	6"		
Bearing	N83W	S80W		
Distance	115 Lks	116 Lks		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK#6 P. 40

Monument at 3140' from east cor in lake - Fnd I.P. M.C.

run W. along fence

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____