


Index No. Z 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 35 Corner common to sections 35, 36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	_____	_____
Diameter	<u>3"</u>	<u>3"</u>	_____	_____
Bearing	<u>N30E</u>	<u>N55W</u>	_____	_____
Distance	<u>21ks.</u>	<u>53ks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN  
Location filed COUNTY SURVEY "E-1"  
Monument 1 New monument  
1921, J. FLYNN, Book "C" P. 119 FND B.T. 1/4" TAM N30E 21  
LKS. AND ORIG. STAKE SET 2 1/2 x 40" I.M. W/CAP

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC  
Washburn Lake - BK # 20 P. 5  
Find 2" I.P. W/CAP 575W 186.7' from NE 2

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>TAM</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>N89E</u>	<u>N54 1/2 W</u>	_____	_____
Distance	<u>5.2'</u>	<u>22.2'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - MILO STEFAN - 1978  
Doc. # 245627  
Set 2" x 60" galvanized steel pipe with  
brass cap. Ties: 12" Cedar N65W 149.60';  
9" Ash N31W 131.00'; 6" Ash N20W  
37.30'; 5" Ash N24E 70.50'; 4" Ash  
N65E 7.40'.

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_