


Index No. CR

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
C.W. 116 Corner common to sections 6



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1919
 Original monument 36" I.D. W/BRASS CAP W 116 1919

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species N. Pine J. Pine
 Diameter 8" 14"
 Bearing N4-30E S4-30W
 Distance 383 LKs 399 LKs

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 2/78 By USFS, Silbaugh
 Location filed USFS Cass Lake BK 4, pg 40
 Monument Iron pipe near old fence corner.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species N. Pine W. Oak Ash W. Oak
 Diameter 6.0 12" 8" 7"
 Bearing N4°E S7°W N84°W N78°E
 Distance 252.78 21.9' 30.1' 55.25'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____