


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 9 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species BIRCH CEDAR
Diameter 8" 5"
Bearing N 15 W NORTH
Distance 10 LKS. 3 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1919 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONAL POSITION - NO ORIG. EVIDENCE
SET 1 X 3/8" I.P. W/BROSS CAP
1/4 54
1/4 59
1919

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species N. PINE
Diameter 12"
Bearing S 1-30 W
Distance 98 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____