Index No. F 4 CASS COUNTY LAND	CORNER RECORD
T. 141 R. 27 M. 574 Coordinates: X	— Y————
NE Mb Corner common to sections 7	
EXISTING	SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1919 NE/16 57	Year of searchBy
Original monument 1X36 111. W/ BEASS 1919	Monument found
	O = Corner
Species W. OAK R. OAK	Original Bearing Trees Found L
170 170	Species
Bearing 566-55 NZ6W	Diameter Bearing
Distance 7/ CKS 16/ CKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of searchBy
Location filed	
Monument	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	
Diameter	
Bearing	
Distance	
Subsequent Corner Restoration Year surveyed By Location filed Monument	Evidence of Subsequent Corner Restoration Found Year of search CERTIFICATE - BILL OKERMAN - 1966 Frund 1" IMM PIPE With Stamped hoass cap. Ties: 9" Oak 5 71 W 10.5'; 7" Oak 5 20E 16.8'; 7" Oak NAIE 13.9'.
<u></u>	
Damas and Alice and Alice	
Remonumentation certificate prepared	—— By —————————————————————————————————