


Index No. F 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N 116 Corner common to sections 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 N 116
Original monument 1x36" I.P. w/BRASS CAP 57158
1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species POPULAR N. PINE _____
Diameter 8" 5" _____
Bearing 569-30E 559-30W _____
Distance 83 LKS 49 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1927 By State Hwy Dept.
Location filed R/W map in Recorder's office - 12 mi. W
Monument Govt non monument 54.8' to Remer
N of G 1336.5' S. of NE 7

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
found 1" iron post 3' long with marked
brass cap. Ties: 8" Poplar 569°30'E 54.78';
Norway Pine 559°30'W 32.34'; 29" W. Pine
N 62°W 140.50'; 6" W Oak 551W 209.20';
N. Pine 4" S 11E 191.20'.

Re monumentation certificate prepared _____

By _____

Filed at _____

Date _____