


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. J 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 16 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>BIRCH</u>	<u>ELM</u>
Diameter <u>6"</u>	<u>14"</u>
Bearing <u>S35E</u>	<u>N33E</u>
Distance <u>10 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONAL POSITION - NO ORIG. EVIDENCE - SET
1/36" I.P. W/ BRASS CAP - 3/8" IN GROUND - FALLS IN 4
OF ROAD

Evidence of Subsequent Corner Restoration

Year of search 1923 By J. H. FLYNN
COUNTY BOOK "D" P 116 FND I.M.

Bearing Trees, Reference Objects 1919

Species <u>W. OAK</u>	<u>W. ASH</u>
Diameter <u>10"</u>	<u>8"</u>
Bearing <u>S35-30W</u>	<u>N67-30E</u>
Distance <u>80 LKS</u>	<u>129 LKS</u>

Bearing Trees, Reference Objects

<u>BL. ASH</u>	<u>BL. ASH</u>	<u>OAK</u>
<u>12"</u>	<u>9"</u>	<u>8"</u>
<u>S77E</u>	<u>N67E</u>	<u>S36W</u>
<u>66.6'</u>	<u>84.5'</u>	<u>53'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____