


Index No. J 4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E116 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
Original monument 1x36" I.P. W/BRASS CAP E116 57  
1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species R. OAK R. OAK  
Diameter 18" 12"  
Bearing N18W S47-30W  
Distance 186 LKS 124 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1922 By J.H. FLYNN  
Location filed COUNTY BOOK "D" P 76  
Monument FND GOVT 12IN CORNER.

Evidence of Subsequent Corner Restoration

Year of search 11/85 By USFS, Krause  
Found Iron & cap, up 12", 80' N. of road, NW oak down, SW oak in road.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

W. Ash W. Oak W. Oak  
7" 4" 9"  
N74°E N36°E N84°W  
53.7' 11.5' 119.1'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Plat - Spawdes Addition, R.F. Schesler 1970

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_