


Index No. K7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
C. N. 1/16 Corner common to sections 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" I.P. w/BRASS CAP ^C N 1/16 | S 17

| Species | Bearing | Trees |
|-------------------------|----------------|-------|
| <u>W. OAK</u> | <u>W. OAK</u> | |
| Diameter <u>18"</u> | <u>12"</u> | |
| Bearing <u>N 36-45E</u> | <u>S 67E</u> | |
| Distance <u>82 LKS</u> | <u>121 LKS</u> | |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| Species | Bearing | Distance |
|---------|---------|----------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

| Species | Bearing | Distance |
|---------|---------|----------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| Species | Bearing | Distance |
|---------|---------|----------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found 1" x 3" iron post with marked brass cap; W. Oak 18" N 36° 45' E 54.12' now a burned stump; 12" W. Oak S 67E 79.86' now 16". Ties: 6" W. Oak S 62E 26.3'; 5" W. Oak N 85E 29.8'; 4" W. Oak N 62E 2.6'; 3" W. Oak N 69W 9.8'.

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____