


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E11416 Corner common to sections 15,16



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Bearing Trees
 Species MAPLE POPLAR
 Diameter 7" 4"
 Bearing N45W N36E
 Distance 8 LKS 12 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1919 By GLO
 Location filed SECRETARY OF STATE
 Monument PROPORTIONAL POSITION SET N36"1/2
W/BRASS CAP
34
S16 515
1919

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species W.OAK W.OAK
 Diameter 10" 12"
 Bearing N78-15E S67-45W
 Distance 75 LKS 44 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found 2" x 3' iron pipe with marked brass
cap; W. Oak 10" N 78°15'E 49.5' found stump;
TIES: 5" Elm N70W 24.68'; W. OAK S76E
11.63'; W. Oak S1E 62.33'.