


Index No. L-25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E11413 Corner common to sections 13 AND 18-14-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>TAM.</u>	<u>S74E</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S8W</u>	<u>S74E</u>	
Distance <u>40 LKS</u>	<u>33 LKS.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/1/1985 By Fredman Hummel  
Location filed Survey Tech Recorder  
Monument 2" 1/8" w/ brass cap in swamp.  
also find 3-1969 B.T.s on Certificate

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Distance
<u>R. Oak</u>	<u>N74E</u>	<u>58.0'</u>
<u>R. Oak</u>	<u>S48E</u>	<u>72.8'</u>
<u>R. Oak</u>	<u>S80W</u>	<u>103.7</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1969  
Set 2" x 5' galvanized steel pipe filled  
with concrete and capped with 3"  
stamped brass tablet. Ties:  
8" R. Oak N74E 58.0'; 7" R. Oak S48E  
72.8'; 8" R. Oak S80W 103.7'.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_