


Index No. 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.E. 116 Corner common to sections 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 E 116  
Original monument 1x36" I.P. w/BRASS C 518 C  
cap 1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>POPULAR</u>	<u>POPULAR</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>N50W</u>	<u>S59W</u>
Distance <u>93 LKS</u>	<u>68 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 10/80 By USFS, Main  
Location filed Cass Lake BK 3, pg. 24  
Monument Found iron & cap, up 10", west  
edge in marsh, 10' from highland,  
GLC BT's are gone.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>W.Oak</u>	<u>W.Oak</u>	<u>W.Oak</u>
Diameter <u>4"</u>	<u>6"</u>	<u>9"</u>
Bearing <u>S53°W</u>	<u>S72°W</u>	<u>N45°W</u>
Distance <u>66.8'</u>	<u>106.63'</u>	<u>46.50'</u>

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_