


Index No. L-M 3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

AP 4 APOT # Corner common to sections 18
1553 (BETWEEN C 14 AND C-N-5-164)



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1919
Original monument 1x36" I.P. W/BRASS 1553 TR 518
CAP. APY 1394

Year of search _____ By _____
Monument found _____

Bearing Trees 1919

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 10/80 By USFS, Krause
Location filed USFS Cass Lake BK 3, pg 25
Monument Found iron & cap, up 10", 60"±
East of woods road, 317' S. of C 14.

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species R. Oak R. Oak R. Oak
Diameter 8" 10" 10"
Bearing N14°W S61°E S26°W
Distance 52.70' 23.50' 36.10'

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Re monumentation certificate prepared _____
Filed at _____

By _____
Date _____