Index No. L-M 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

N-S 1/64 Corner common to sections 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919

Original monument 1X36" I.P w/BRASS CAP S18 TR 1743 AP4 AP1 TR 1394 | S17

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species			1919
Diameter			
Bearing			
Distance			

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 10/80 By USFS, Brame

Location filed USFS Cass Lake, BK 3, pg 27

Monument Found iron & Cap, up 12"

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	W. Oak	W. Oak	W. Oak
Diameter	4"	6"	6"
Bearing	S13°W	N74°W	N17°W
Distance	33.98'	27.45'	13.85'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____