


Index No. 08-9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X _____ Y _____
CCWC Corner common to sections 20



EXISTING SURVEYS

Original Government Survey
Year surveyed 1919
Original monument 2x36" IRON/BRASS CC SRO | NWC
CAP | 1919

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species CEDAR TAM
Diameter 10" 10"
Bearing N86W S57W
Distance 173 LKS 145 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____