Index No. 54

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 1/16 Corner common to sections 30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919

Original monument 1X36" IRON POST W/BRASS CAP.

NE 1/16 S30 1919

Bearing Trees

Species	POPLAR	POPLAR		
Diameter	6"	8"		
Bearing	N45E	S14-45W		
Distance	59 LKS	129 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1980 By C. Krause

Location filed US.F.S. - Cass Lake

Monument Found brass capmonument and rotted poplar stump N45E 39.0'

1982 - Gary Stevenson - Corner Certificate

Bearing Trees, Reference Objects

Species	Elm	Ash	W. oak	
Diameter	8"	6"	5"	
Bearing	N48E	S49E	S13E	
Distance	81.43'	80.48'	102.22'	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - Filed by USFS Doc #279154 1984 - dated 1982

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____