


Index No. V 14-15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
MC # 13 Corner common to sections R7,34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Species	Bearing	Trees
<u>OAK</u>	<u>OAK</u>	
<u>14"</u>	<u>8"</u>	
<u>N7W</u>	<u>S68W</u>	
<u>21LKS</u>	<u>43LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1974-1978 By MILLO STEFAN
Location filed PLAT OF SURVEY "E-72"
Monument 2"x5" GALV IR. W/ 3" BRASS CAP.

Evidence of Subsequent Corner Restoration

Year of search 1993 By Terry Freeman
found 2"x5" galvanized iron pipe w/ 3" brass cap.
left as found. 5-4-94 Cert. Filed by Terry Freeman,
RLS 21367, DOC. #357315.

Bearing Trees, Reference Objects

Species	W. OAK	W. PINE	W. PINE	SIGN POST
Diameter	<u>24"</u>	<u>15"</u>	<u>19"</u>	<u>STEEL</u>
Bearing	<u>N18E</u>	<u>N82W</u>	<u>S71W</u>	<u>EAST</u>
Distance	<u>22.4'</u>	<u>20.8'</u>	<u>17.1'</u>	<u>1.2'</u>

Bearing Trees, Reference Objects

White Oak stump	Norway Pine	White Pine	White Pine
<u>24"</u>	<u>5"</u>	<u>20"</u>	<u>25"</u>
<u>N18E</u>	<u>N</u>	<u>N82W</u>	<u>S71W</u>
<u>22.4'</u>	<u>14.04'</u>	<u>20.70'</u>	<u>17.01'</u>
(1976 USFS BT)		(1976 USFS BT)	(1976 USFS BT)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____